DEPARTMENT OF THE NAVY

NAVAL AIR WARFARE CENTER AIRCRAFT DIVISION

IN HEIZY HEFER TO

Ser 4.a.8.700B551-2/0007

26 JAN 1955

Head, Consolidated Automated Support System/Common Automatic Test Equipment Software Support from:

Activity Branch, Naval Air Warfare Center Aircraft Division (Code 4.8.8.7000551-2), rhight any 547,

Lakehurst, NJ 08733-5105

RELEASE OF PRAGRAM DEVELOPMENT STATION (PDS) SYSTEM SOFTWARE PART NUMBER Such

(P/N) NAEC-PDS-001

(1) Support Software Change (SSC) Number 2736 _ YZK fix
(2) PDS Installation Instructions Eacl:

(2) PDS Installation Instructions

1. The PDS system software, P/N NAEC-PDS-001, is now available for use. The NAEC-PDS-001 consists of PDS operating software, VULCAN 4.0.

- 2. The data packages, in the form of kits which consist of the system software tape, the appropriate documentation, etc., are being forwarded to all system software users in accordance with Naval Air System Communic approved procedures, enclosure (1).
- 3. Enclosure (2) is the installation instructions used to download the NAEC-PDS-001 system software generation tape onto a PDS station. It is recommended that users duplicate a copy of NAEC-PDS-001 as a working copy. The original master copy of NAEC-PDS-001 should be kept in a safe place.
- 4. Point of contact is Mr. P. Yeung, Code 4.8.8.700B, DSN 624-4871 or commercial (732) 323-4671, or E-mail yeungpp@lakehurst.navy.mil.

W. KNOPP

. Distribution: NAVAVNDEPOT North Island NAVAVNDEPOT Jacksonville NAVAVNDEPOT CHERRY POINT Aircraft Equipment Maintenance Squadron Cold Lake Canada

Copy to: (wo encl)

COMNAVAIRSYSCOM Patuxent River (PMA-260D24)

NAVAVNDEPOT North Island (M. Salcedo)

•					N C	
		2. Date Propared:		3. SC	r no.	
1. Originator Name and Address:					1-601-59	
Naval Air Warfare Center Aircraft Division U. S. Highway 547		January 19, 1999				
akehurst, N. J. 08733				}		
Building 551-2				1		
*AAA A # R.7						
752-323-1841	ni: 5. Title of Ch	rage:				
. Contractor No. & Line Iter			m Salmare			
N/A	Program Deve	lopment System (PDS) System (PD	8. Host Test	Station	9. UUT PIN	
6. Software Configuration In	en Nomenciature & PA	7. In Production	0132000			
		() Yes [X] No	ATE		N/A	
PDS System Saftware	10 Doc	umentation Affected (TPS)				
	10. 200					
		Document No.				
Title						
11. Description of Change System Problem Report NAE 12. Need for Change: Fix was putting for Year 2000		d to fix the Year 2000 proble	m. 			
System Problem Report NAE					lems Affected	
System Problem Report NAE 12. Need for Change: Fix was putting for Year 2000) problem	d to fix the Year 2000 proble		uration i	tems Affected	
System Problem Report NAE) problem			uration l	tems Affected	
System Problem Report NAE 11. Need for Change: Fix was putting for Year 2000 13. Effect on Production De) problem	14. Other systems/So		wallon i	lems Affected	
System Problem Report NAE 12. Need for Change: Fix was putting for Year 2000 13. Effect on Production De N/A	problem	14. Other systems/So N/A	Itware Config		tems Affected	
System Problem Report NAE 11. Need for Change: Fix was putting for Year 2000 13. Effect on Production De	problem	14. Other systems/So N/A 15. Retrobt b. Estimated Deliver	Itware Config	c. L	ocations Aliected	
System Problem Report NAE 12. Need for Change: Fix was putting for Year 2000 13. Effect on Production De N/A	problem	14. Other systems/So N/A 15. Retrofit	Itware Config	c. L		
System Problem Report NAE 12. Need for Change: Fix was puring for Year 2000 13. Effect on Production De N/A 8. Estimated Cost (O&MN,	problem livery Schedule APN, etc.)	14. Other systems/So N/A 15. Retrofit b. Estimated Deliver 31 January 19, 1999	Itware Config y Schedule	c. L Suc	ocations Aliected	
System Problem Report NAE 12. Need for Change: Fix was putting for Year 2000 13. Effect on Production De N/A 8. Estimated Cost (O&MN,	problem livery Schedule APN, etc.)	14. Other systems/So N/A 15. Retrofit b. Estimated Deliver 31 January 19, 1999 17. Title	y Schedule	c. L. Suc	ocations Affected attachment (1)	
System Problem Report NAE 12. Need for Change: Fix was puring for Year 2000 13. Effect on Production De N/A 8. Estimated Cost (O&MN,	problem livery Schedule APN, etc.)	14. Other systems/So N/A 15. Retrofit b. Estimated Deliver 31 January 19, 1999 17. Title	y Schedule	c. L. Suc	ocations Affected attachment (1)	
System Problem Report NAE 12. Need for Change: Fix was puring for Year 2000 13. Effect on Production De N/A 8. Estimated Cost (O&MN,	problem livery Schedule APN, etc.)	14. Other systems/So N/A 15. Retrofit b. Estimated Deliver 31 January 19, 1999	Schedule The ATE/TPS	c. L. Suc	ocations Affected attachment (1)	
12. Need for Change: Fix was putting for Year 2000 13. Effect on Production De N/A 8. Estimated Cost (O&MN, \$35,000 (prior funding) 16. Submitting Activity Aut	problem livery Schedule APN, etc.)	14. Other systems/So N/A 15. Retrofit b. Estimated Deliver 31 January 19, 1999 17. Title Head, Support Equiport VAIR Approval/Disapprays	Itware Config y Schedule	c. L. Suc	ocations Affected attachnient (1) vice Engineering F	
System Problem Report NAE 11. Need for Change: Fix was puring for Year 2000 13. Effect on Production De N/A 8. Estimated Cost (O&MN,	problem Itvery Schedule APN, etc.) horizing Signature 18. NA	14. Other systems/So N/A 15. Retrofit b. Estimated Deliver 31 January 19, 1999 17. Title Head, Support Equip	Itware Config y Schedule	suc Sin-Sen	ocations Affected attachnient (1) vice Engineering F	

Site Affected By SCP Number 1-001-99

NAVAVNDEPOT North Island
NAVAVNDEPOT Cherry Point NC//JJJ//
NAVAVNDEPOT Jacksonville FL//324/614//
Aircraft Equipment Maintenance Squadron - Williamtown Australia
Cold Lake Canada